Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: BIG GUMBO CREEK CTB

Field Name: N/A Well File #:

Date Incident: 3/14/2014 Time Incident: 11:00 Facility ID Number: 413779-04

County: BOWMAN Twp: 130 Rng: 106 Sec: 5 Qtr:

Location Description:

Submitted By: Stacy Aguirre Received By:

Contact Person: Stacy Aguirre

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident Other

Release Contained in Dike Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

 Oil
 340
 Barrels
 340
 Barrels

 Brine
 220
 Barrels
 220
 Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Tuesday, March 24, 2015 Page 1 of 3

Potential Environmental Impacts:

location material

Action Taken or Planned:

liquid was completely contained in the flare pit; repaired the separator dump valve; recovered all liquid from the flare pit, returned liquid to the production tanks

Wastes Disposal Location: returned to facility production tanks

Agencies Involved: NDIC, Allison Christensen, was notified via telephone at 14

NDIC, Allison Christensen, was notified via telephone at 14:41

Updates

Date: 3/17/2014 Status: Reviewed; Followup Required Staff: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. However, due to the large quantity of materials spilled, followup is necessary.

Tuesday, March 24, 2015 Page 2 of 3

Date: 3/17/2014 Status: Inspected Staff: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The weather was 50 °F, with wind from the northeast at 10-15 mph. I walked around the flare area and did not see any evidence of product leaving the pits. All products were contained on site. No further followup is required at this time.

Tuesday, March 24, 2015 Page 3 of 3